Maryland Historical Trust

Maryland Inventory of Historic Properties number: 402-1402	
Name: Stone Chapeled over Little Repe	Crle

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

MARYLAND HISTORICAL Eligibility Recommended X	AL TRUST Eligibility Not Recommended
Criteria:AB CD Considerations:A	$_B$ $_C$ $_D$ $_E$ $_F$ $_G$ $_None$
Comments:	
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001
Reviewer, NR Program:Peter E. Kurtze	Date:3 April 2001

Jun

Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust Name and SHA No. Stone Chapel Road over Little Pipe Creek/CL363 Location: Street/Road Name and Number: Stone Chapel Road City/Town: Avondale Vicinity <u>x</u> County: Carroll Ownership: __State_x_County__Municipal__Other This bridge projects over: __Road__Railway x Water__Land Is the bridge located within a designated district: yes x no__NR listed district__NR determined eligible district _locally designated__other Name of District_ **Bridge Type:** __Timber Bridge _Beam Bridge__Truss-Covered__Trestle Timber-and-Concrete __Stone Arch Metal Truss __Movable Bridge _Bascule Single Leaf__Bascule Multiple Leaf __Vertical Lift __Retractile__Pontoon x Metal Girder <u>x</u> Rolled Girder <u>Rolled Girder Concrete Encased</u> __Plate Girder __Plate Girder Concrete Encased

MHT Number CARR-1482

Maryland Inventory of Historic Properties

Metal Suspension	
Metal Arch	
Metal Cantilever	
Concrete Concrete ArchConcrete SlabConcrete BeamRigid FrameOther Type Name	1

Description:

Describe Setting:CL363 carries Stone Chapel Road over Little Pipe Creek in Carroll County, Maryland. Stone Chapel Road runs in a generally north-south direction at this location; Little Pipe Creek flows generally east-west. The bridge is located in a rural setting. There is a 20th century townhouse development, several residences and an evergreen farm visible from the bridge. Little Pipe Creek has a wooded channel bank at this location.

Describe Superstructure and Substructure:CL363 is a single span steel beam bridge with a concrete deck and bituminous concrete wearing surface on the roadway. There is a single strand W-beam guardrail mounted on wide flange steel beam posts mounted on a concrete curb. The approach roadway is paved with asphalt, and there is a continuous W-beam guardrail on both sides of the bridge deck and on the approaches.

The superstructure is supported by concrete abutments and wing walls. There is slight scouring on the southern abutment. The west elevation has a wooden cattle guard attached to the exterior beam.

The 1995 inspection report lists the bridge as being in satisfactory to good condition, with hairline cracks and spalled concrete on the underside of the deck, rust and peeling paint, and some minor cracks and spalls in the abutments and wing walls. The report recommends cleaning and painting of the underside of the deck, and minor repairs to the abutments. It also recommends placing rip rap with geotextile fabric around the east end of the south abutment to protect it against further scour.

Discuss Major Alterations: There is no documentary evidence in any of the county bridge files to indicate that major alterations have been made to CL363. There has been routine maintenance done to the structure over the past years.

History:

When Built:1936

Why Built:local transportation needs

Who Built:

Why Altered:n/a

Was this bridge built as part of an organized bridge building campaign:yes

Surveyor Analysis:

This bridge may have NR significance for association with:

__A Events __B Person

__C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:It is not likely that CL363 was constructed for any reason other than the need for a more stable structure at this particular crossing of Little Pipe Creek.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area: Construction of CL363 would have allowed a heavier live load to pass this bridge on Stone Chapel Road, but it probably did not have a significant impact on growth or development in the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district: This area is not eligible for historic designation.

Is the bridge a significant example of its type:CL363 may be considered a significant example of its type because of its good condition and lack of major alterations.

Does the bridge retain integrity of the important elements described in the Context Addendum: The rolled longitudinal I-beams, a primary character defining element, have never been replaced. The same is true for the floor system and deck, both secondary character defining elements. Minor repairs have been made to the beams, as well as cleaning and painting.

Concrete abutments are considered primary character defining elements. The abutments of CL363 have never had any major repair work done to them either. Minor cracks and spalling have been repaired on a routine basis.

Because of the lack of major alterations, and the fact that the bridge is still in good condition may indicate that CL363 does retain its original integrity.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why:CL363 is a typical steel beam and concrete abutment bridge of the early 20th century, and is not particular to any one manufacturer, designer or engineer.

Should this bridge be given further study before significance analysis is made and why:CL363 may warrant further study, or comparison to other steel beam bridges in the area, before significance analysis is completed.

Bibliography:

Carroll County

v.d. Bridge Inspection Files.

Greiner, Inc.

1995 Historic Bridge Inventory Form.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.


United States Geological Survey

1953 7.5' New Windsor Quadrangle, photorevised 1971.

Surveyor:

Name: <u>Stephanie L. Bandy</u> Date: <u>September 1995</u>
Organization: <u>State Highway Admin.</u> Telephone: (410) 321-2213

Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory # CARR-1482 CL 363 Name Stone Chape/Rd. over Little Pipe Creek County/State Carroll Co. Md.
Name of Photographer D. Dieny Date 2-95
Description north approach looking south

12 * 0科 =

Number 36 of 32 4



Inventory #CARL-1482
CL 363 Name Stone, Chape/ Rd. over Little Pipe Cr. County/State Carrol/ Co. Md. Name of Photographer D. Dieh/
Name of Photographer D. Dieh/
Date 2-95
Location of Negative <u>SHA</u>
Description east elevation looking west
Number 37 of 372

10.01 m



Inventory # CARR-1482	
Name Stone Chape Rd. over Little Pipe Crek County/State Carroll Co. Md.	
County/State <u>Carroll</u> Co. Md.	
Name of Photographer	
Date 2-95	
Location of NegativeSHA	
Description west elevation looking east	
	(S + OF)
Number 37 of 37	



" 1800-1407		
Inventory # CARR-1482		
CL363		
Name Stone Chape/Rd. over Little Pipe Creek		
County/State Carroll Co. Md.		
Name Stone Chape Rd. over Little Pipe Creek County/State Carroll Co. Md. Name of Photographer D. Diehl		
Date 2-95		
Date _ 2 _ 13		
Location of NegativeSHA		
Description South approach looking north		
Number of 29	2)	*0 -1)